

Land slide and living conditions of minority in the northern part of mountain area, Nepal

*Yuji Kuwahara¹

1.Department of Urban and Civil engineering, school of Engineering, Ibaraki University

In Apr.2015, M7.8 earthquake occurred in Nepal. It was confirmed the building damage in an urban area and the landslide damage in a mountainous region by a field survey in 2015. Especially, in mountainous region, we found the minority people who can't get accident support. So, today, I will talk about the field survey results in Nepal.

Keywords: seismic hazard, land slide, minority, satellite image