

2018年台湾花蓮地震の地震動と花蓮市の地盤構造推定

Strong motions and estimation of the subsurface soil structure for the 2018 Hualien earthquake in Taiwan

*山田 真澄¹、長 郁夫²、郭 俊翔³、林 哲民³、宮腰 研⁴、郭 雨佳⁴、林田 拓己⁵、松元 康広⁶、Mori James¹、顔 銀桐⁷、郭 耕杖⁸

*Masumi Yamada¹, Ikuo Cho², Chun-Hsiang Kuo³, Che-min Lin³, Ken Miyakoshi⁴, Yujia Guo⁴, Takumi Hayashida⁵, Yasuhiro Matsumoto⁶, James Mori¹, Yin-Tung Yen⁷, Keng-Chang Kuo⁸

1. 京都大学防災研究所、2. 産業技術総合研究所、3. 国家地震工程研究中心、4. 地域地盤環境研究所、5. 建築研究所、6. 構造計画研究所、7. 中興公司、8. 国立高雄科技大学

1. Disaster Prevention Research Institute, Kyoto University, 2. National Institute of Advanced Industrial Science and Technology, 3. National Center for Research on Earthquake Engineering, 4. Geo-Research Institute, 5. Building Research Institute, 6. Kozo Keikaku Engineering, 7. Sinotech Engineering Consultants, 8. Kaohsiung university of Science and Technology

The 2018 Hualien earthquake occurred around 23:50, February 6, 2018 (local time). The depth of the event was about 10 km and the moment magnitude was 6.4 (USGS). Crustal deformation in the Hualien basin was clearly observed in the InSAR image (e.g., GSI 2018, Hashimoto 2018). The rupture propagated along the Milun fault from north to south and the northern part of the Longitudinal Valley fault was also ruptured. Particularly, the discontinuity of the interference fringes at the Milun fault was clear on the InSAR image.

In Hualien city, the middle-rise four buildings collapsed during the earthquake, due to the collapse of the pillars at the first floor. They were located at the place where discontinuous fringes were observed in the InSAR images. There is a possibility that the discontinuous displacements or ground motions in the vicinity of the fault affect on the damage of the buildings (NARlabs 2018).

In order to understand the cause of building damage in Hualien city and the heterogeneous subsurface soil structure in the Hualien basin, we performed microtremor array measurement on October 20-26, 2018. We performed the measurement at every 100-200 m along the EW section of the basin. At each measurement point, we used 5 seismometers to obtain the phase-velocity dispersion curves at the shallow subsurface structure. In total, we measured microtremors at 64 observation points and obtained the phase-velocity dispersion curves and H/V spectra.

Our profile shows that the peak of the H/V spectra is about 1-2 Hz along the measurement line, which probably corresponds to the basement at the depth of 50-100m. The average Vs at the depth of 10-30m is about 200-400 m/s. There is a clear difference between the east and west side of the Milun fault: at the west side of the fault, there is a soft soil deposit on the shallow surface (10m) with the average Vs less than 200m/s. At the east side of the fault, the soft layer with the Vs<400m/s is very thin. Therefore, we estimated the engineering bedrock of the west side of the Milun fault is deeper than the east side. This difference of the basin thickness is consistent with the movement of the Milun fault during the 2018 Hualien earthquake estimated from the InSAR image.

キーワード：花蓮地震、強震動、表層地盤構造、常時微動

Keywords: Hualien earthquake, Strong motion, Subsurface soil structure, Microtremor

