

## Investigation of damage trace of the 2005 Fukuoka Earthquake -Part 3-

YAMADA, Nobuyuki<sup>1\*</sup> ; NOGUCHI, Haruka<sup>1</sup>

<sup>1</sup>Fukuoka University of Education

After the disaster of 2011, the existence such as the monuments which ticked away the teaching of the ancestor who conveyed a disaster was performed a close-up of in each place. The history of the past valuable teaching and disasters such as monuments might be forgotten with time. Therefore, it is an opportunity to raise disaster prevention awareness to convey history of disaster and a disaster sign.

We investigated the damage trace of the earthquake of the Fukuoka northwest offing in 2005. In this study, we surveyed in twenty-one sites, we was able to confirm the damage trace of the earthquake concerned in ten sites. And we made the map which could take a walk through these damage traces.

Keywords: the 2005 Fukuoka Earthquake, damage trace